



Several broken battery packs for DS125 and DS160 strobes have been traced to a material inconsistency. Battery packs produced between September 2007 and November 2008 are subject to this flaw in the central black plastic mounting piece.

A date code with the format MM/YY is etched on each pack opposite the Product Number 4066.5. Packs produced after November 2008 or which have been returned to Ikelite for any reason since December 2008 have been updated to a newer style toggle pawl. This appears to have corrected the issue.



We recommend the updating of these battery packs as a preventative maintenance measure. If you have a broken toggle pawl or a battery pack within the above date range in its original condition, toggle replacement kits are available. Please contact us directly if you live within North America. Otherwise, please contact your local Ikelite distributor

<http://www.ikelite.com/support/faq/ds-strobes.html>