Advanced statistics

Report

Criteria Demo Customer 1

Searched for Job

Searching rules Job - Client is Demo Customer 5 - MC

Jobs found 5

Measurements 25

Samples 337

Filters Standard deviation

Produced by MeasureColor

Greenville 200 Capri Ct 29609

864-370-2990

Jobs

9.16.10	Description	Gloss Roll COLOR VERIF GRACoL2006		Date Tolerance Measurements	9/16/2010 11:35:39 AM GRACoL 3
3	Name Description Reference		Date Tolerance Measurements	8/26/2011 7:38:4 CMC 2:1 2	13 PM
3	Name Description Reference		Date Tolerance Measurements	8/29/2011 1:13:2 CMC 2:1 16	23 PM
3	Name Description Reference		Date Tolerance Measurements	8/26/2011 8:06:4 CMC 2:1 2	16 PM
3	Name Description Reference		Date Tolerance Measurements	8/26/2011 8:06:5 CMC 2:1 2	55 PM

Scores

Solid	Average Peah high Peak low Spread	86.00 % 86 86 0	Standard deviation In standard deviation Outside of standard deviation	2.92 21 1
Dot gain	Average Peah high Peak low Spread	74.00 % 74 74 0	Standard deviation In standard deviation Outside of standard deviation	5.42 21 1
Paperwhite	Average Peah high Peak low Spread	100.00 % 100 100 0	Standard deviation In standard deviation Outside of standard deviation	0.00 22 0
Balance	Average Peah high Peak low Spread	98.00 % 98 98 0	Standard deviation In standard deviation Outside of standard deviation	0.73 19 3
Overprint	Average Peah high Peak low Spread	98.00 % 98 98 0	Standard deviation In standard deviation Outside of standard deviation	0.60 20 2

Delta-E

C100	Average Spread Peah high Peak low	4.34 0.2 4.47 4.27	Standard deviation In standard deviation Outside of standard deviation	1.21 21 4
K100	Average Spread Peah high Peak low	10.96 1.26 11.68 10.42	Standard deviation In standard deviation Outside of standard deviation	2.75 21 4
M100	Average Spread Peah high Peak low	1.74 0.88 2.51 1.63	Standard deviation In standard deviation Outside of standard deviation	0.72 23 2
PG 1679W	Average Spread Peah high Peak low	7.93 0.39 8.19 7.8	Standard deviation In standard deviation Outside of standard deviation	1.69 20 2
PG 1680W	Average Spread Peah high Peak low	7.59 0.27 7.66 7.39	Standard deviation In standard deviation Outside of standard deviation	1.54 21 1
PG 1681W	Average Spread Peah high Peak low	8.52 1.13 9.45 8.32	Standard deviation In standard deviation Outside of standard deviation	1.77 21 1
Y100	Average Spread Peah high Peak low	4.28 1.04 5.15 4.11	Standard deviation In standard deviation Outside of standard deviation	1.43 22 3

Density differences

C100	Average Spread Peah high Peak low	-0.05 0.014 -0.042 -0.056	Standard deviation In standard deviation Outside of standard deviation	0.05 21 4
K100	Average Spread Peah high Peak low	0.08 0.125 0.101 -0.024	Standard deviation In standard deviation Outside of standard deviation	0.09 22 3
M100	Average Spread Peah high Peak low	0.17 0.014 0.18 0.166	Standard deviation In standard deviation Outside of standard deviation	0.11 21 4
PG 1679W	Average Spread Peah high Peak low	-0.25 0.011 -0.241 -0.252	Standard deviation In standard deviation Outside of standard deviation	0.07 20 2
PG 1680W	Average Spread Peah high Peak low	-0.06 0.009 -0.052 -0.061	Standard deviation In standard deviation Outside of standard deviation	0.01 20 2
PG 1681W	Average Spread Peah high Peak low	-0.34 0.012 -0.335 -0.347	Standard deviation In standard deviation Outside of standard deviation	0.08 20 2
Y100	Average Spread Peah high Peak low	0.05 0.065 0.066 0.001	Standard deviation In standard deviation Outside of standard deviation	0.05 22 3

Actual dotgains

C100	25 % Target Average Peah high Peak low	12.28 16.71 16.92 16.35	Standard deviation In standard deviation Outside of standard deviation	0.38 16 6
C100	50 % Target Average Peah high Peak low	17.19 21.53 21.70 21.36	Standard deviation In standard deviation Outside of standard deviation	0.19 16 6
C100	30 % Target Average Peah high Peak low	13.70 12.97 12.97 12.97	Standard deviation In standard deviation Outside of standard deviation	3.68 1 2
C100	70 % Target Average Peah high Peak low	14.90 12.14 12.14 12.14	Standard deviation In standard deviation Outside of standard deviation	2.28 1 2
K100	25 % Target Average Peah high Peak low	15.20 20.07 20.50 16.91	Standard deviation In standard deviation Outside of standard deviation	2.51 23 2
K100	50 % Target Average Peah high Peak low	19.65 20.69 21.14 20.43	Standard deviation In standard deviation Outside of standard deviation	1.19 23 2
K100	10 % Target Average Peah high Peak low	7.30 5.56 5.56 5.56		2.51 I 2
K100	75 % Target Average Peah high Peak low	14.50 13.49 13.49 13.49	Standard deviation In standard deviation Outside of standard deviation	1.14 1 2
K100	90 % Target Average Peah high Peak low		In standard deviation).77 I 2
M100	25 % Target Average Peah high Peak low	12.40 19.72 19.95 19.41	Standard deviation In standard deviation Outside of standard deviation	0.37 18 4
M100	50 % Target Average Peah high Peak low	17.17 21.32 21.48 21.16	Standard deviation In standard deviation Outside of standard deviation	0.22 16 6

MeasureColor

M100	30 % Target Average Peah high Peak low	13.70 10.88 11.07 10.68	Standard deviation In standard deviation Outside of standard deviation	2.53 2 1
M100	70 % Target Average Peah high Peak low	14.90 11.44 11.84 11.04	Standard deviation In standard deviation Outside of standard deviation	1.97 2 1
PG 1679W	25 % Target Average Peah high Peak low	17.25 4.84 5.15 4.27	Standard deviation In standard deviation Outside of standard deviation	0.65 14 8
PG 1679W	50 % Target Average Peah high Peak low	21.88 15.28 16.61 14.49	Standard deviation In standard deviation Outside of standard deviation	1.20 14 8
PG 1680W	25 % Target Average Peah high Peak low	17.71 14.66 14.98 14.26	Standard deviation In standard deviation Outside of standard deviation	0.46 15 7
PG 1680W	50 % Target Average Peah high Peak low	21.97 15.64 15.82 15.42	Standard deviation In standard deviation Outside of standard deviation	0.27 14 8
PG 1681W	25 % Target Average Peah high Peak low	17.47 8.93 9.08 8.72	Standard deviation In standard deviation Outside of standard deviation	0.26 18 4
PG 1681W	50 % Target Average Peah high Peak low	21.84 13.15 13.38 12.74	Standard deviation In standard deviation Outside of standard deviation	0.45 18 4
Y100	25 % Target Average Peah high Peak low	12.30 17.66 18.10 17.10	Standard deviation In standard deviation Outside of standard deviation	0.55 16 6
Y100	50 % Target Average Peah high Peak low	17.07 18.97 19.20 18.76	Standard deviation In standard deviation Outside of standard deviation	0.30 14 8
Y100	30 % Target Average Peah high Peak low	13.70 6.21 6.63 5.80	Standard deviation In standard deviation Outside of standard deviation	1.75 2 1
Y100	70 % Target Average Peah high Peak low	14.90 7.36 7.36 7.36	Standard deviation In standard deviation Outside of standard deviation	2.39 1 2

Dotgain differences

C100	25 % Average Peah high Peak low	4.53 4.97 3.52	Standard deviation In standard deviation Outside of standard deviation	0.91 21 1
C100	50 % Average Peah high Peak low	4.51 4.80 4.01	Standard deviation In standard deviation Outside of standard deviation	0.89 21 1
C100	30 % Average Peah high Peak low	-0.73 -0.73 -0.73	Standard deviation In standard deviation Outside of standard deviation	3.68 1 2
C100	70 % Average Peah high Peak low	-2.76 -2.76 -2.76	Standard deviation In standard deviation Outside of standard deviation	2.28 1 2
K100	25 % Average Peah high Peak low	5.06 5.50 1.91	Standard deviation In standard deviation Outside of standard deviation	2.61 22 3
K100	50 % Average Peah high Peak low	1.03 1.54 -0.17	Standard deviation In standard deviation Outside of standard deviation	1.21 23 2
K100	10 % Average Peah high Peak low	-1.74 -1.74 -1.74	Standard deviation In standard deviation Outside of standard deviation	2.51 1 2
K100	75 % Average Peah high Peak low	-1.01 -1.01 -1.01	Standard deviation In standard deviation Outside of standard deviation	1.14 1 2
K100	90 % Average Peah high Peak low	-0.90 -0.90 -0.90	Standard deviation In standard deviation Outside of standard deviation	0.77 1 2
M100	25 % Average Peah high Peak low	7.51 7.96 6.64	Standard deviation In standard deviation Outside of standard deviation	1.45 21 1
M100	50 % Average Peah high Peak low	4.26 4.64 3.77	Standard deviation In standard deviation Outside of standard deviation	0.82 21 1
M100	30 % Average Peah high Peak low	-2.82 -2.63 -3.02	Standard deviation In standard deviation Outside of standard deviation	2.53 2 1
M100	70 % Average Peah high Peak low	-3.46 -3.06 -3.86	Standard deviation In standard deviation Outside of standard deviation	1.97 2 1

MeasureColor

PG 1679W	25 %			
	Average	-13.30	Standard deviation	3.13
	Peah high		In standard deviation	21
	Peak low	-14.68	Outside of standard deviation	า 1
PG 1679W	50 %			
	Average	-6.86	Standard deviation	2.60
	Peah high	-5.39	In standard deviation	20
	Peak low	-8.96	Outside of standard deviation	2
PG 1680W	25 %			
	Average	-3.18	Standard deviation	1.02
	Peah high	-2.79	In standard deviation	19
	Peak low	-3.80	Outside of standard deviation	3
PG 1680W	50 %			
1 4 100011	Average	-6.74	Standard deviation	1.53
	Peah high		In standard deviation	21
	Peak low	-7.41	Outside of standard deviation	1
DC 4 404W	25.0/			
PG 1681W	25 % Average	-9.03	Standard deviation	1.97
	Peah high		In standard deviation	21
	Peak low	-9.88	Outside of standard deviation	1
		7.00		•
PG 1681W	50 %		6	
	Average	-9.27	Standard deviation	2.10
	Peah high	-8.81	In standard deviation	21
				21
Y100	Peah high Peak low 25 %	-8.81 -10.90	In standard deviation Outside of standard deviation	21 n 1
Y100	Peah high Peak low 25 % Average	-8.81 -10.90 5.56	In standard deviation Outside of standard deviation Standard deviation	21 n 1
Y100	Peah high Peak low 25 % Average Peah high	-8.81 -10.90 5.56 6.18	In standard deviation Outside of standard deviation Standard deviation In standard deviation	21 n 1 1.11 20
Y100	Peah high Peak low 25 % Average	-8.81 -10.90 5.56	In standard deviation Outside of standard deviation Standard deviation	21 n 1 1.11 20
Y100 Y100	Peah high Peak low 25 % Average Peah high Peak low 50 %	-8.81 -10.90 5.56 6.18 4.40	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation	21 n 1 1.11 20
	Peah high Peak low 25 % Average Peah high Peak low 50 % Average	-8.81 -10.90 5.56 6.18 4.40	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation	21 1 1 1.11 20 2
	Peah high Peak low 25 % Average Peah high Peak low 50 % Average Peah high	-8.81 -10.90 5.56 6.18 4.40 1.97 2.32	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation In standard deviation	21 1 1 1.11 20 2 0.46 19
	Peah high Peak low 25 % Average Peah high Peak low 50 % Average	-8.81 -10.90 5.56 6.18 4.40	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation	21 1 1 1.11 20 2 0.46 19
	Peah high Peak low 25 % Average Peah high Peak low 50 % Average Peah high	-8.81 -10.90 5.56 6.18 4.40 1.97 2.32	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation In standard deviation	21 1 1 1.11 20 2 0.46 19
Y100	Peah high Peak low 25 % Average Peah high Peak low 50 % Average Peah high Peak low 30 % Average	-8.81 -10.90 5.56 6.18 4.40 1.97 2.32 1.48	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation Standard deviation	21 1 1 1.11 20 2 0.46 19
Y100	Peah high Peak low 25 % Average Peah high Peak low 50 % Average Peah high Peak low 30 % Average Peah high	-8.81 -10.90 5.56 6.18 4.40 1.97 2.32 1.48	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation In standard deviation In standard deviation	21 1 1 1.11 20 2 0.46 19 3
Y100	Peah high Peak low 25 % Average Peah high Peak low 50 % Average Peah high Peak low 30 % Average	-8.81 -10.90 5.56 6.18 4.40 1.97 2.32 1.48	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation Standard deviation	21 1.11 20 2 0.46 19 3
Y100	Peah high Peak low 25 % Average Peah high Peak low 50 % Average Peah high Peak low 30 % Average Peah high	-8.81 -10.90 5.56 6.18 4.40 1.97 2.32 1.48	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation In standard deviation In standard deviation	21 1 1 1.11 20 2 0.46 19 3
Y100 Y100	Peah high Peak low 25 % Average Peah high Peak low 50 % Average Peah high Peak low 4 Average Peah high Peak low	-8.81 -10.90 5.56 6.18 4.40 1.97 2.32 1.48	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation In standard deviation In standard deviation	21 1 1 1.11 20 2 0.46 19 3
Y100 Y100	Peah high Peak low 25 % Average Peah high Peak low 50 % Average Peah high Peak low 30 % Average Peah high Peak low 70 % Average Peah high	-8.81 -10.90 5.56 6.18 4.40 1.97 2.32 1.48 -7.49 -7.07 -7.90	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation Outside of standard deviation In standard deviation In standard deviation In standard deviation In standard deviation	21 1.11 20 2 0.46 19 3 1.75 2 1
Y100 Y100	Peah high Peak low 25 % Average Peah high Peak low 50 % Average Peah high Peak low 30 % Average Peah high Peak low 70 % Average	-8.81 -10.90 5.56 6.18 4.40 1.97 2.32 1.48 -7.49 -7.07 -7.90	In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation Outside of standard deviation Standard deviation In standard deviation In standard deviation Standard deviation Outside of standard deviation Standard deviation Outside of standard deviation	21 1.11 20 2 0.46 19 3 1.75 2 1