


Case 580 Side-Shift Backhoe Aftermarket Pins Bushes



Description	Kgs	K-Set Part No.	Price Each (ex GST)	Reference	OEM No.
A PIN, BOOM (wasD140093)	4.0	580SK-PIN-A	\$ 190	P70G102P	142698A1
BUSH, BOOM (2)	0.8	580SK-BUSH-AB	\$ 56	B90F70-38	D151071
“ , BEFORE 0047600 (2)	“	“ “ “	\$ 58	B90F70-33	D136569
BUSH, TOWER INNER (2)	0.5	580SK-BUSH-ATI	\$ 56	B90F70-24	D135742
BUSH, TOWER OUTER (2)	0.5	580SK-BUSH-ATO	\$ 48	B90-70-24	D135741
B PIN, LIFT CYL TO TOWER	4.6	580SK-PIN-B	\$ 130	P70-156C	112294A1
BUSH, TOWER (2)	0.8	580SK-BUSH-BT	\$ 66	B90F70R39	D135740
BUSH, LIFT CYLINDER (2)	0.3	580SK-BUSH-BC	\$ 56	B80-70-25	D144421
C PIN, LIFT CYL TO BOOM	4.5	580SK-PIN-C	\$ 120	P50-290C	D135023
BUSH, CYL ROD (2)	1.5	580SK-BUSH-CB	\$ 66	B70-50-78	D148798,D145080
BUSH, BOOM	0.3	580SK-BUSH-CR	\$ 41	B60-50-40	D141555
D PIN, ARM CYL TO BOOM	3.7	580SK-PIN-D	\$ 130	P50-240C	D138022
BUSH, BOOM (2)	0.8	580SK-BUSH-DB	\$ 54	B70-50-54	D138047,D137217
BUSH, ARM CYL (2)	0.8	580SK-BUSH-DC	\$ 40	B67-50-40	D141555
“ , BEFORE 0014389 (2)	0.6	“ “ “	\$ 40	B67-50R46	G108417
E PIN, ARM CYL TO ARM	3.7	580SK-PIN-E	\$ 130	P50-240C	D138022
PIN, CYL TO EXT ARM	3.0	580SK-PIN-EX	\$ 90	P50-199C	D141666
BUSH, ARM (2)	0.8	580SK-BUSH-E	\$ 54	B70-50-54	D137217
BUSH, EXTENDING ARM	0.5	580SK-BUSH-EX	\$ 43	B70-50-34	D141389
BUSH, CYL ROD (2)	0.5	580SK-BUSH-ER	\$ 41	B60-50-40	D141555
“ , BEFORE 0014389 (2)	0.6	“ “ “	\$ 40	B67-50R46	G108417
F PIN, BOOM TO ARM	9.0	580SK-PIN-F	\$ POA	P70G301T	D132494
BUSH, BOOM	0.9	580SK-BUSH-FB	\$ 66	B90-70-44	D137218
BUSH, BOOM, SLOTTED	0.9	580SK-BUSH-FBS	POA	B90-70M44	D135739
BUSH, EXTENDING ARM (2)	0.8	580SK-BUSH-FX	\$ 66	B90F70R39	D135740

<https://axleaddict.com> Step by Repair Guide with photos. Case Backhoe Hydraulic Cylinder Repairs