



SUUNTO



Suunto has recalled all of the first series of Suunto Vytec computers after discovering a software bug in the model's Simplan function. It has asked all customers who purchased version 21, serial numbers 205000 to 223700, to contact their local dealer or the manufacturer for a replacement.

Suunto discovered that when the unit was in nitrox mode and the Simplan function was used before the dive, it was possible to lose vital data. It said that divers could be at risk because of this fault and that the computers should be returned.

'Allocation of replacements is on the basis of the date the Vytecs are received at Suunto,' said John Sinclair of Suunto Diving UK. 'In case there is a critical return date, users are advised to telephone Suunto first to check on availability.'

Transmitters are not to be returned as they are not affected.'

If the Vytec is returned directly to Suunto, a daytime address and phone number needs to be supplied and, if possible, the name of the dealer from whom it was purchased. Phone 01420 587272

Courtesy of
Aug 2002

