

# WELLMASTER

## DRIVE SHOES


Part Number:

**M5001650**

Description:

**DRIVE SHOE**

**4 1/2" X 4" CABLE TOOL WELD ON 5.200" O.D.**



**WELLMASTER Pipe & Supply Inc.**

1494 Bell Mill Road, P.O. Box 456, Tillsonburg, Ontario, Canada, N4G 4J1

Phone: (519) 688-0500  
Fax: (519) 688-0563  
Email: wells@wellmaster.ca

P.O. Box 2663, Buffalo, New York, U.S.A., 14240-2663



**1-800-387-9355**

[www.wellmaster.ca](http://www.wellmaster.ca)

