

COMMON WEATHER
030 663 7330
OFFICE
630-428-1967
HOME

IDNS RADIOLOGICAL DUTY OFFICER
STANDARD OPERATING PROCEDURE

Revision 6
June 21, 1999

RDO INCIDENT REPORT FORM

Date: 11-9-00 Time: 1907 Telecommunicator: CHAPMAN RDO: WRIGHT - 1915 HRW

Reported by JEFF ROMAN ^{TSC} BRAIDWOOD 815-941-4810
(Name) (Title) (Telephone Number)

Company/Agency: IDNS

Incident Date: 11-9-00 Incident Time: DISCOVERED THIS AFTERNOON Location: NE OF BRAIDWOOD STATION -

Incident Description: BACKING BARRIER BROS. ON GROUND + IN WATER
COBALT 60 DUMP EASEMENT ON SMILEY ROAD, WILL TAKE
4-5 DAYS TO CLEAR DITCH, WILL USE STAGE DIESEL DRIVE PUMPS

Radioactive Material(s): Nuclide COBALT 60 Activity JONITH
Nuclide TRITIUM Activity _____
Nuclide _____ Activity _____
Nuclide _____ Activity _____

Reported Radiation Levels & Instruments Used: SAMPLES SENT TO TELEDON ^{CIA STAPLIN}

Additional Hazards: LINE GOES ACROSS PRIVATE PROPERTY
WILL TAKE 4-5 DAYS TO CLEAR THE DITCH
FEAR STIMPINS PAGER 815-767-0047
815-634-2164 AT BR PLANT 815-458-2201 X 2980
(Name and title of Contact Person at the Scene) (Telephone Number)

Personnel injuries, status of treatment: NO INJURED OR CONTAMINATED
Location of injured personnel: PERSONS

Other response agencies notified or on-scene (including points of contact): _____

FOR TRANSPORTATION INCIDENTS ONLY

Container Size: _____ Type: _____ Label Type: _____
Carrier's Name: _____ Shipper's Name: _____
Consignee's Name: _____
Consignee's Address: _____
Vehicle Identification: _____
Additional Information: _____

On-Scene Weather: WIND 20.6 MPH
TEMP 32.4° LIGHT SHOWERS
Directions to Incident Scene: ON SMILEY ROAD, TOWARDS PRODUCTION PLANT,
NORTHEAST OF PLANT
250 YARDS SOUTH OF PROPERTY LINE - NONE TO
EAST, SOUTH, WEST / STANDING WATER BELOW
LLD FOR 150 TO 200

NOTIFICATIONS:

REAC Commander: Time / Date: _____
Director: Time / Date: _____
PIO: Time / Date: _____
DEPUTY DIRECTOR: TIME/DATE: 1924 NOVEMBER 9, 2000

6